

## EXPERIENCE, QUALITY & DEPENDABILITY

## QUIPP NewsCom® Windows-10 Upgrade

NEWSCOM<sup>®</sup> for Windows 7/10 was released in February 2014, but only for some inserters. Until recently, we have been unable to update Inserters with Automation Direct I/O, as the manufacturer has ceased updating their drivers. As far as we know, only SLS-1000 inserters have this brand of I/O (there may be a few exceptions). There are two types of Automation Direct I/O in use in NewsCom<sup>®</sup> inserters. See the following photos to confirm if your system uses this I/O.





Newer style I/O

Older style I/O

We have recently built our own interface to these I/O modules and have now made it possible for you to upgrade your system to 64-bit Windows 10.

Inserters with Opto-22 PAMUX I/O (not shown) have been upgradable since February of 2014.

The upgrade is complex and will likely require a site visit by QUIPP technicians because the I/O layout/mapping within NewsCom® must be completely redone and tested. We will confirm this on a case-by-case basis. Future upgrades, like to Windows 10+, will not likely require another site visit.

With your NewsCom® Software Support Plan, we can offer you a discount for the visit and there is no charge for the NewsCom® software conversion from the 32-bit version to the 64-bit version. There is a \$500 charge for a license to be able to run a secondary Operating System that will run side-by-side with Windows on machines with the I/O shown above.

If you are considering this upgrade, it is also likely a good time to consider replacing your critical but aging PC systems that are running NewsCom<sup>®</sup>.

Another thing to consider is that while we had been able to continue providing updates to the Windows XP version of NewsCom<sup>®</sup>, we "hit a wall" in February of 2017 when the tools used for development hit their end of life. These machines are still supported, but we can no longer provide updates for them.

For more information, send an email to NewsCom@quipp.com or contact sales: 305-304-1985